

TAKE WAX

Description:

It is a mix of special solvents, for eliminating protective paraffin waxes. It does not damage the parts it is used on. This product is to be used in cold processes.

Directions for use:

Use pure as is.

<u>Remarks:</u>

Please follow the instructions on the safety data sheet for the safe handling of the product.

Technical characteristics:

Appearance and color: liquid clear yellow Smell: characteristic pH: not available Flash point: >100°C Relative density: 0.8930 g/cm3 Solubility in water: not soluble Lipid solubility: not soluble

> FRA-BER s.r.l. The Laboratory Chief

The original document is signed and can be examined at the Company Headquarters.